

Work History

Registration/Fleet ID	LS21XUK	Asset No.	AAFV5574
Make/Model	MERCEDES-BENZ CLA DIESEL SHOOTING BRAKE (2019) CLA 220d AMG Line 5dr Tip Auto		
Latest Odo Reading	68283	Odo Reading Date	18 Apr 2024
Contract Start Date	23 Apr 2021	Contract End Date	22 Jul 2024

Date	Service Centre	Line Item Description
18 Apr 2024	Sterling Garage Ltd Newbury	MOT - Class IV Cars (Up To 8 Passenger Seats) Test Date:18 Apr 2024 Certificate No:368513676593
Odo Reading	68283	
Invoice No.	LS21XUK	
Authority Ref.	8860644	
Job Ref.	134863342	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
09 Apr 2024	Mercedes Benz Of Newbury	3 year Service - 2019/- CLA Class (118)
Odo Reading	67315	
Invoice No.	85019015	
Authority Ref.	8851912	
Job Ref.	134602869	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
08 Apr 2024	ATS NEWBURY (005)	P 1 Goodyear 225/45 R 18 Y EAGF1AS6XL
Odo Reading	67433	P 1 Wheel Balance
Invoice No.	11510304	P 1 Casing Disposal
Authority Ref.		P 1 Tubeless Valve
Job Ref.	11053469	P 1 Goodyear 225/45 R 18 Y EAGF1AS6XL
Job Status	Complete	P 1 Wheel Balance
		P 1 Casing Disposal
		P 1 Tubeless Valve

Date	Service Centre	Line Item Description
31 Jul 2023	Mercedes Benz Of Newbury	Air Cleaner - Remove & Refit, Air cleaner/filter - assy
Odo Reading	52699	Filters - Remove & Refit, Fuel filter - complete
Invoice No.	85014300	Auto Gearbox Oil - Remove & Refit, Automatic transmission oil
Authority Ref.	8627459	46500 mls/kms Service - 2019/- CLA Class (118)
Job Ref.	127861087	Hydraulic Fluid - Remove & Refit, Hydraulic fluid (Brake)
Job Status	Payment Requested	Disc - Remove & Refit, Disc - front (pair)

Date	Service Centre	Line Item Description
26 Oct 2022	ATS NEWBURY (005)	P 1 Michelin 225/45 R 18 Y PILOT SPOR 5 XL (CA2-72dB)
Odo Reading	37751	P 1 Wheel Balance
Invoice No.	11274019	P 1 Casing Disposal
Authority Ref.		P 1 Tubeless Valve
Job Ref.	9877592	
Job Status	Complete	

Date	Service Centre	Line Item Description
21 Oct 2022	Mercedes Benz Of Newbury	31000 mls/kms Service - 2019/- CLA Class (118)
Odo Reading	37645	
Invoice No.	85009461	
Authority Ref.	AC	
Job Ref.	121057959	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
01 Aug 2022	ATS NEWBURY (005)	P 1 Wheel Alignment - Electronic
Odo Reading	34412	P 1 Tubeless Valve
Invoice No.	11224414	P 1 Wheel Balance
Authority Ref.		P 1 Michelin 225/45 R 18 Y PILOT SPOR 5 XL (CA2-72dB)
Job Ref.	9691377	P 1 Casing Disposal
Job Status	Complete	P 1 Tubeless Valve
		P 1 Casing Disposal
		P 1 Michelin 225/45 R 18 Y PILOT SPOR 5 XL (CA2-72dB)
		P 1 Wheel Balance
		P 1 Casing Disposal
		P 1 Wheel Balance
		P 1 Michelin 225/45 R 18 Y PILOT SPOR 5 XL (CA2-72dB)
		P 1 Tubeless Valve
		P 1 Michelin 225/45 R 18 Y PILOT SPOR 5 XL (CA2-72dB)
		P 1 Wheel Balance
		P 1 Casing Disposal
		P 1 Tubeless Valve

Date	Service Centre	Line Item Description
25 Mar 2022	Mercedes Benz Of Newbury	31000 mls/kms Service - 2019/- CLA Class (118)
Odo Reading	27403	Wash/Wipe Systems - Remove & Refit,
Invoice No.	85006393	Windscreen wiper - blade/s
Authority Ref.	8202630	Adblue - Remove & Refit, AdBlue fluid
Job Ref.	116474143	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
01 Oct 2021	Mercedes Benz Of Newbury	1 year Service - 2019/- CLA Class (118)
Odo Reading	14436	AdBlue fluid
Invoice No.	85003593	
Authority Ref.	8049505	
Job Ref.	112919234	
Job Status	Payment Requested	